

49 Bedford Street P.O. Box 445 East Bridgewater, MA (508) 456-4232

Stoughton Fire Department – Station No. 1 Prospect Street Full Meeting #14 Agenda November 16, 2023, 10:30am

Agenda

1. Old Business

- a. Review of Project Meeting #13 Minutes Open Items
- b. Schedule Update
- c. PCO/RFQ Log Review
- d. Safety Update
- e. Certified Payroll Update

2. New Business

- a. D&W Non-Conforming Work Log (update)
- b. No Smoking Policy

End of Meeting



49 Bedford Street P.O. Box 445 | East Bridgewater, MA | (508) 456-4232

Stoughton Fire Department – Station No. 1 Prospect Street Project Meeting #13 Minutes November 2, 2023, 10:30am

Name	Department/Company	Attendance
Chief Michael Carroll – (MC)	Stoughton Fire Department	X
Assistant Chief Jack Macomber - (JM)	Stoughton Fire Department	
Captain George O'Neil - (GO)	Stoughton Fire Department	X
Fran Bruttaniti – (FB)	Town of Stoughton	X
Paul Giffune – (PG)	Town of Stoughton	
Marc Tisdelle – (MT)	Town of Stoughton	
Craig Horsfall – (CH)	Town of Stoughton	X
Nick Dufresne – (ND)	Town of Stoughton	X
Glen Gollrad – (GG)	Dore + Whittier	X (online)
Kevin Seniw – (KS)	Dore + Whittier	X
Donald Walter – (DW)	Dore + Whittier	X (online)
John Thompson – (JT)	Dore + Whittier	X (online)
Taylor MacDonald – (TM)	Pomroy Associates	X
Alex Murphy – (AM)	Pomroy Associates	X
Bob Rice – (BR)	Pomroy Associates	X
Rick Pomroy – (RP)	Pomroy Associates	
Lyle Coghlin – (LC)	CTA Construction	X
Terry Vieux – (TV)	CTA Construction	X
Isaiah Sylvan – (IS)	CTA Construction	X

ACTION BY	ITEM#	<u>DESCRIPTION</u>	DATE OPENED	DATE CLOSED
СТА	3	Construction Schedule	l —	
CTA	3	Construction Schedule 2 week look ahead See attached 10/19 Updates: - Water line install complete, along with pressure and chlorination test. - Crushing rock, (material is being tested by Briggs which will be paid by Digit). CTA will notify town if Digit is working Saturday 10/21 Also received a complaint from abutter stating construction started before 7:00 am last Saturday. - Roof Drains — will start shortly. - Roof Pads — Preparation is underway, with concrete pour next week. - Roof Blocking / Roof Penetrations — Roof blocking complete. - Roof Vapor Barrier — Load material on roof next week. - Sewer line to start Tuesday 10/24 — will start at road and make way to building. - Steel phase 1 almost complete - Exterior walls 1st floor at main building, once complete AVB install will start - Exterior walls 2md floor almost complete - Exterior walls - south and west next week - Balcony — Shoring company will be onsite today to review will try and pour next week. - Interior Metal Stud Framing — Overhead metal track will start along with interior stud wall framing. - First Floor Level — underground plumbing delay has affected the sequencing of the project. O Plumbing Update on Venting - PCO #28 cost to make proposed changes and does not include any above ground piping changes — not including impacts on other areas like 2nd floor, etc. Plumbing Engineer stated the design and install is per code. - CH to speak with the building/plumbing inspector and help set up a meeting to discuss the plumbing inspector's concerns. - Requesting written documentation of code issues from plumbing inspector concerns. - Requesting written documentation of code issues from plumbing inspector of concerns. - Requesting written documentation of code insues from plumbing inspector of concerns. - Requesting written documentation of code issues from plumbing inspector of concerns. - Requesting written documentation of code insues from plumbing inspector. - Construction Schedule Update 10/19: Per LC construction schedu	<u>OPENED</u> 5/18/23	CLOSED 10/19/23
		 approval. Water line work (on Prospect St.) Update Completed. Item Closed 		

ACTION BY	ITEM#	<u>DESCRIPTION</u>	DATE	DATE
			<u>OPENED</u>	CLOSED
CTA	3A	 Rock & Ledge excavation quantities 10/19: no update Rock Ledge Quantities: Updates Unsuitable: 5,500 allotted; 4301 (committed) (surveyed number) Open Rock and Ledge: 950 allotted; 950 committed. 10/19: no update Mockup update – Per JK wrong strap anchors were delivered for the windows. Waiting on delivery for correct ones. Wall base flashing, exterior sealants, rigid insulation along with hat channel will follow. 11/2/23 – Per BR rocks were removed with trenching for utilities. BR will receive slip from Digit. BR will update total. CO #3 D&W has updated and will be forwarded to CTA. 	5/18/23	
Record	4	Utilities - Initial gas and electrical submission complete. - D&W provided contact info to CTA. CTA started coordination for install. 10/19: No new updates 11/2/23 –CTA is in conversation with gas and electric company.	5/18/23	
Town	6	 Owner Vendors ECO Tech – First Site visit completed. 10/19: Waiting on schedule – D+W to follow up Treatment plan for Fall is open. Loma update 10/19: Loma paperwork filed, no updates 11/2/23 – Eco Tech has not been on site, D&W to verify. 		

ACTION BY	ITEM#	<u>DESCRIPTION</u>	DATE	<u>DATE</u>
			<u>OPENED</u>	CLOSED
DW&CTA	7	Submittals Hot list review Oil/Water Separator -MWRA Jurisdiction – check permitting and inspection before backfilling. 10/19/23 – Hot List Submittals Sliding Glass Door Hardware Product Data Metal Doors & Frame Submittal Package (2) – HOT Leeching Galley Additional Drawings Storefront Product Data Concrete Light pole base shop drawing Elevator steel shop drawings and Calcs Fire Protection Shop Drawings and Calcs Metal Composite Wall Panel System Cold-formed metal framing shop drawing (interior) Metal Wall Panel Shop Drawing (Revision) Sectional Doors Manufacturer Letter (meets design specs) Elevator Vent Color Sample Louver Product Data and Color Chart Vibration Isolators Product Data	5/18/23	10/19/23
DW&CTA	8	 RFI's Open RFI's Hot list review 10/5/23: #51 – Plumbing Inspection – Wet Venting GGD to follow up 10/19/23 – awaiting update #54 – Radiant Floor Sensor Location #55 – Anchor Bolt – RFI #40 follow up 10/19/23 - RFI forthcoming for above overhead doors structural drawings show CMU and architectural drawings show metal stud framing.	5/18/23	10/19/23

ACTION BY	ITEM#	<u>DESCRIPTION</u>	DATE OPENED	DATE CLOSED
All	9	 PCO's Open PCO's Change Order #2 to be processed. (PCO's 12, 13, 14, 16, 18, 21, 22, 23 and 24 – 10/5: D+W to finalize – will be part of the rec for September 10/19/23: PCO #11 – Ledge Removal Further discussion needed on quantities and differences between Dig-It and Nitsch analysis. #26 – VRF Upsize Fitness Room – awaiting response #27 – Old Box Culvert Removal – awaiting response 	5/18/23	10/19/2
All	10	 Material Testing ● Breaks for 6/30/23 – under design strength – Swiss hammer results? ● 7/17/23 & 7/19/23, 8/7 and 8/24, low breaks. ● Structural Field Report items 9/21/23 – Low concrete breaks – better with 56 day report – Structural engineer to make a site visit for inspection 10/5/23 – All steel reports good; up to date; final steel inspection with CTA 10/19/23 – dense grade – ledge sent for testing − Briggs – steel testing and rebar testing ongoing − Affidavits (attestations) for building department from D+W/consultants on footings and foundations − Field reports and letter from Geotech to building dept as well. − CTA updating foundation as-built Building Inspections − JK to send 3 week lookahead to building inspector − As-built for foundations to be sent − Affidavits for foundations and excavation 10/19/23 – CTA to coordinate with building inspector with upcoming inspections. Engineering Dept. – drainage − Ledge and drainage – any changes? − Nitsch to follow up 	5/18/23	10/19/23

ACTION BY	ITEM#	<u>DESCRIPTION</u>	DATE	DATE
			<u>OPENED</u>	CLOSED
CTA	11	 Payroll Certificates and Reporting Send to tmacdonald@pomroyassociates.com and amurphy@pomroyassociates.com 10/19/23 - No items discussed. 11/2/23 - No issues 	5/18/23	11/2/23
All	12	Preconstruction meetings 10/5/23: CTA to notify the town for new underground utilities and structures so they can inspection before any back filling. 10/19/23: no updates 11/2/23 -No future meetings	5/18/23	11/2/23
D+W	19	Fire Hydrant – D+W provided an PR additional hydrant at back of site for training purposes. 10/19 – PCO for hydrant is coming 11/2/23 – PCO approved.	10/5/23	11/2/23
D+W	20	D+W Non-conforming Log - CTA to provide completed items on excel log. 10/19: to be sent out 11/2/23 -Per TV excel file shared last week and will be updated. TM requested a revised progress copy to be sent each week.	10/5/23	
D+W	21	As-Built foundation plan – Per CTA the plan might be finished by Tuesday 10/10. 10/19: to be sent out 11/2/23 – Completed and sent to town.	10/5/23	11/2/23
СТА	22	Per D&W there needs to be a running up to date document for the as-builts. 10/19: JK working on these. 11/2/23 – As-built for drainage system ongoing	10/5/23	
ALL	24	Utilities: In this order • Water line Completed • Sewer line Tuesday 10/24 - completed. • Electrical conduit – To start next week. • Gas Line – Final install Note: The Riverhawk survey for the sewer line invert was 1'-0" higher than what excavated. Digit reconfigured the pitch and Nitsch verified and approved. As-built drawing will be issued. New Business	10/5/23	
Record	13.1	JK is out on short term disability for 3 months. IS is the on-site superintendent and will continue in JK's absence.	11/2/23	11/2/23

Record	13.2	Schedule	11/2/23	11/2/23
		• 2-week look-ahead		
		Mockup		
		 Install Window – Has been installed to meet 		
		after meeting to discuss window clips.		
		o Install Wall Base Flashing		
		 Install Exterior Window Sealants and Strip-In 		
		Flashing		
		o Install Exterior Rigid Insulation & Hat Channel		
		Sitework		
		o Excavate & Install Drainage Structures, Pipe, &		
		System		
		 Install Sewer Structures and Piping 		
		 Install remaining water service to building 		
		 Unsuitables Removal Front of Building 		
		 Electrical Duct Bank 		
		Structure Steel		
		 Install remaining Roof Decking 		
		Building Roof Level		
		 Prep & Place Concrete Roof Pads 		
		 Install Roof Blocking and Penetrations 		
		 Install Main Roof Vapor Barrier 		
		Building 2 nd Floor Level		
		o Shore and Place Balcony Concrete Deck (TBD)		
		o Install Interior Metal Stud Framing		
		Building 1st Floor Level		
		O Under-Slab Rough Electrical (Main Bldg.)		
		Excavate and Backfilling Under slab Rough Install Companie College College		
		o Install Concrete Column Collars		
		 Gravel Grading and Prep Insulation / VB / Wire Mesh/Formwork		
		I (II) (III) (III)		
		 Install Masonry HM Frames CMU shear walls 		
		(Maint. Bay) Under slab Rough		
		Exterior Walls – South (CL 1-7 Maint. Bay /		
		Apparatus)		
		Exterior Wall Sheathing		
		Exterior Wall AVB		
		Exterior Walls – East		
		 Sheathing installation 		
		 Exterior Wall AVB at sheathing 		
		 Exterior East CMU Wall 		
		Exterior Walls – North		
		Exterior Wall Metal Framing & Blocking		
		o AVB at sheathing		
		Exterior North CMU Wall Low Exterior Wells West		
		Exterior Walls – West		
		Exterior Wall CMUExterior Walls – South (CL 1-7 Maint. Bay /		
		Apparatus)		
		Exterior Wall Metal Framing & Blocking		
		District wan recan Flaming & Distring		
		Overall Updated Construction Schedule – CTA will		
		provide by end of week. TM requested a full-size		
<u>. </u>			•	

ACTION BY	ITEM#	<u>DESCRIPTION</u>	DATE OPENED	DATE CLOSED
		sheet for the trailer. Per CTA there is no change in the overall completion date.	OFENED	CLOSED
Record	13.3	 Hot Submittals Cold Formed Metal Framing – D&W submitted back to CTA. Ship Ladder & Rails at Equipment Platform Wood Casework Product Data Wood Door Physical Sample Storefront Shop Drawing Storefront Hardware Product Data Acoustic Ceiling Shop Drawings Resilient Flooring Samples Fluid-Applied Flooring Product Data (substitution D&W to verify it's a equal product) Tile & Mat Submittal Package Personnel Storage Locker Product Data & Shop Drawing Exterior Foundation Insulation Product Data 	11/2/23	
Record	13.4	Hot RFI's Radiant Floor Sensor Location Details on T0.01 NEMA Rating E2.10	11/2/23	11/2/23
Record	13.5	PCO's None open	11/2/23	11/2/23
Record	13.6	PR's • 18 - Traffic Signal Package: CTA is pricing, separate line item included in budget. • 20 – Removal of Eyewash	11/2/23	11/2/23
Record	13.7	ASI's – D&W to proceed with ASI's for coordination issues.	11/2/23	11/2/23
Record	13.8	Material Testing – Briggs has been on site every day for ½ day for rebar, mortar/grout testing. BR to reschedule testing company for 3 days with Mehul's permission.	11/2/23	
Record	13.9	Certified Payroll Update – No issues	11/2/23	11/2/23
Record	13.10	Unsuitable Material at Concrète Apron Nick Lanney (Geotechnical Engineer) was onsite to directed Digit where to excavate and remove unsuitable material. Digit will provide a survey of material removed. There was no ledge during excavation.	11/2/23	11/2/23

Record 13.11 Concrete Slab (House Side) – Per LC should be completed in 2-3 weeks. Per TM before concrete slabs are poured verify final inspection with all inspectors. Record 13.12 Exterior Column Covers – CTA to speak with Folan. 11/2/23 D&W 13.13 Signal at Prospect St Original PR showed a separate duct bank. D&W to speak with GGD if the spare in the original electrical duct bank can be used. D&W / D&W to provide ASI Existing Tree to be reviewed D&W to review after meeting. CTA 13.15 Sewer Line Prospect Street Manhole Cover Manhole Cover	ACTION BY	ITEM#	DESCRIPTION	DATE	DATE
completed in 2-3 weeks. Per TM before concrete slabs are poured verify final inspection with all inspectors. Record 13.12 Exterior Column Covers – CTA to speak with Folan. 11/2/23 D&W 13.13 Signal at Prospect St Original PR showed a separate duct bank. D&W to speak with GGD if the spare in the original electrical duct bank can be used. D&W / D&W to provide ASI Existing Tree to be reviewed D&W to review after meeting. CTA 13.15 Sewer Line Prospect Street Manhole Cover 11/2/23					<u>CLOSED</u>
D&W 13.13 Signal at Prospect St Original PR showed a separate duct bank. D&W to speak with GGD if the spare in the original electrical duct bank can be used. D&W / Table Property Fence Line — Table Property Fence Line Prospect Street The property Fence Line — Table Property Fence Line Prospect Street The property Fence Line — Table Property Fence Line Prospect Street The property Fence Line — Table Property Fence Line Prospect Street The property Fence Line — Table Pr	Record	13.11	completed in 2-3 weeks. Per TM before concrete slabs are poured verify final inspection with all	11/2/23	11/2/23
Original PR showed a separate duct bank. D&W to speak with GGD if the spare in the original electrical duct bank can be used. D&W /	Record	13.12	Exterior Column Covers – CTA to speak with Folan.	11/2/23	
CTA • D&W to provide ASI • Existing Tree to be reviewed D&W to review after meeting. CTA 13.15 Sewer Line Prospect Street • Manhole cover says drain, change to Sewer Manhole Cover	D&W	13.13	 Original PR showed a separate duct bank. D&W to speak with GGD if the spare in the 	11/2/23	
Manhole cover says drain, change to Sewer Manhole Cover		13.14	D&W to provide ASIExisting Tree to be reviewed D&W to review	11/2/23	
CTA 1016 A P 15 P 1 C 10 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	СТА	13.15	Manhole cover says drain, change to Sewer	11/2/23	
CTA 13.16 As-Built Drawings – Certification from Nitsch for stormwater. Per TV As-built drawing should be done next week and forwarded to D&W.	СТА	13.16	· ·	11/2/23	
Record 13.17 Briggs Inspection Request – As agreed upon all inspection requests will be in writing. All future inspections will be forwarded to the building department.	Record	13.17	inspection requests will be in writing. All future inspections will be forwarded to the building	11/2/23	11/2/23
Record 13.18 Testing Agency Memo – In order to complete his affidavit, Mehul has requested a memo from Briggs stating there are no non-conforming issues as it relates to testing and inspections. Also, Nick Lanney can provide the same document.	Record	13.18	Testing Agency Memo – In order to complete his affidavit, Mehul has requested a memo from Briggs stating there are no non-conforming issues as it relates to testing and inspections. Also, Nick Lanney	11/2/23	
Record 13.19 Oil/Water Separator per IS will be installed this Monday paperwork has been filled out and pictures and video will be documented during testing of structure. MWRA will send a permit. IS stated Kneeland has coordinated all items.	Record	13.19	Monday paperwork has been filled out and pictures and video will be documented during testing of structure. MWRA will send a permit. IS stated	11/2/23	
Next Full Meeting: 11/16/23					
Working Group: 11/9/23					

Jiking Group. 11/7/23